

Cross-Band Modification

Change C821 to 0.022uF Change R828 to 22K

This modification will fix the over deviated/muffled transmitted audio while using the Cross-Band Repeater